AGE OF BUILDINGS ASSOCIATED WITH CHRIST OUR HOPE

St Joseph Church	1879
St Joseph's Rectory	1881
Church Office Boonville	1890
Gill Hall	1910
St Patricks Church	1886, Original building, New addi- tions, 1918 & 1950s
Thrift Shop	1962
Keiffer Hall	1960s?
St. Mary's Church Otter Lake	1921

Collections from Memorial Day to Labor Day

Date	St Mary's	St Partick's	St Joseph's
5/26	\$530.00	\$1,096.00	\$3,539.00
6/2	\$591.00	\$970.00	\$2,783.00
6/9	\$331.00	\$986.00	\$2,872.00
6/16	\$369.00	\$913.00	\$2,019.00
6/23	\$446.00	\$1,138.00	3,036.00
6/30	\$569.00	\$1,100.00	\$3,637.00
7/7	\$616.00	\$1,290.00	\$3,002.00
7/14	\$678.00	\$1,289.00	\$2,397.00
7/21	\$740.00	\$925.00	\$5,198.00
7/28	\$596.00	\$977.00	\$1,944.00
8/4	\$533.00	\$1,269.00	\$2,866.00
8/11	\$757.00	\$848.00	\$2,233.00
8/18	\$632.00	\$1,366.00	\$4,967.00
8/25	\$570.00	\$1,011	\$2,212.00
9/1	\$628.00	\$1171.00	\$2,153.00
Total	\$8,586.00	\$16.349.00	\$44.858.00

Capital Improvements from 2021-Present.

Nm Insulation of Basement Rectory	\$2,100.00
Rebuild side porch	\$3,000.00
New roof for Side Porch	\$8,900.00
Garage Roof	\$1,778.00
Gill Hall Roof	\$17,997.61
Upgrade heating in Rectory	\$11,497.00
Office Bathroom Repair	\$689.95
Gill Hall ceiling replacement due to water damage	\$9,127.26
Painting for Ceiling in Gill Hall	\$1,500.00
New LED Lights for Gill Hall	\$1,742.98
Gill Hall Kitchen and Bathroom Flooring	\$2,578.83
Front and side porch Repairs (Rectory)	18,441.87
Gill Hall Wheelchair Ramp	\$3,167.08
New Roof at St. Patrick's Church	\$37,665.23
New Roof at Thrift Shop	\$6,589.65
Renovations to upstairs classroom in Gill Hall	\$3,200.00
New Garage Doors at St Mary's	\$2,773.86
Re-key Doors at St Mary's	\$369.26
New Bell System to Replace old system that wasn't Functioning.	\$11,480.00
New windows in Gill Hall	\$8,839.33
Addition on Garage for Plow Truck	\$4,936.72
New Commercial Stove in Gill To replace non-functioning one	\$3,750.00
New HVAC Minisplit for heat/AC in Keifer Hall (Grant Subsidy)	\$5,621.00
New Electrical Panel (Grant Subsidy)	\$5,600.00
New Lighting upstairs in Keifer Hall	\$450.00
Purchase shed for St Patrick's Cemetery for Storage of cemetery supplies to eliminate transporting supplies	\$8,950.00
TOTAL	\$171,074.23

STATE OF THE PARISH REPORT

The Parish of (Christ Our Hope)

St Joseph's Boonville St Patrick's Otter Lake St Mary of the Snows Otter Lake

THE CARE OF SOULS

Number of registered parishioners	446	
October 2024 count	Forestport 75-90 Boonville 200-220	
Seating capacity of the church	300 Boonville, 200 Forestport, 200 Otter Lake	
Population trend of the parish	See Parish Vitality	
Parish vitality	St Joseph's in Boonville, Est. 1879 is situated in the village of Boonville. The Church is populated with many young families with children as well as a large middle-aged population. The average attendance is between 250 -300 per weekend. (Vigil and Sunday Mass) Adult Catechesis programs are held during Advent, Lent, and Easter. Average attendance is between 15-20 people. Weekly Faith Formation is held in Boonville at Gill Hall where Approx. 70 kids are registered 2024/25 School Year.	
	St Patrick's, Est. 1848 is situated in the village of Forestport NY. The Church is populated with an older generation of parishioners with weekly attendance averaging approximately 75-120 depending on time of year. Spring and summer are generally more populated than winter and fall.	
	St Mary of the Snows, Est. 1921 is situated on Rt 28 in the Town of Forestport, and in the hamlet of Otter Lake. The Church is populated with a variety of middle-aged and older parishioners. There are about 3-5 young families with children that attend the church regularly. This operates as a summer chapel from Memorial Day to Labor Day serving the needs of those coming north to their summer camps. The average attendance is between 45-60 per weekend.	
Mass Schedule	Weekend Mass Schedule: Saturday Vigil 4PM Boonville Sunday 8:00AM Forestport Sunday 9:30AM Bonville Sunday 11:15AM Otter Lake (Memorial Day—Labor Day)	

FINANCIAL SITUATION

Average yearly expenses	\$260,316.22
Average yearly income	\$275,725.98
Maintenance of buildings and grounds	\$15-20k ???
Ratio of expenses for maintenance/bills vs. expenses for ministry	75% Maintenance 25% Ministry
Savings (restricted vs. unrestricted)	85,000 Unrestricted 20,000 (Approx)
Other	See Risk Management Concerns

RISK MANAGEMENT CONCERNS

St Mary's Otter Lake

Front retaining wall is cracking and needs repair/replacement

Gutters need repair/replacement

Peeling paint on aluminum siding needs to be addressed

Mary grotto/statue needs repointing

Garage wood siding is rotted on bottom

2. St Patrick's Forestport

Thrift Shop

Plumbing needs work sewer pipe significantly rusted. (will need replacing)

Fix drywall in living room ceiling from previous leak. (Leak fixed roof repaired 2022)

Fireplace/chimney needs inspection, hasn't been used in many years.

Back deck will need to be repaired/ strengthened.

Wooden Siding is peeling and needs to be scraped and painted.

Church

Stucco needs repainting in parts due to mold

Eves need to be painted as paint is peeling

Sidewalk to handicap entrance will need to be repaired in the future for safety.

Church Floor will need to be addressed in the future as is crumbling. (floor is asbestos)

Keifer Hall

Roof replacement, active leaking Evaluate foundation and fill cracks in foundation.

Removal of capped chimney (not in use)

Removal of old antenna on roof.

Blacktop driveway due to annual stone washout

Update lighting in hall many lights ballasts have went bad.

Update non-working security lights outside building

3. St Joseph Boonville

Gill Hall

Cosmetic painting inside

Evaluate electrical, main feed from church, box overloaded, breakers trip occasionally

Replace boarded up basement windows as plywood is rotted.

Church

Foundation work required ASAP (front foundation has severe cracking and pieces falling out)

Repair stonework on outdoor sign

Boilers currently 13 years old (inspection done annually)

Sacristy window frames are rotted and outside glass is cracking.

Side entrance near rectory to church needs repair. Porch rotting, same side door rotted on bottom

Front door locking mechanism broken

Front sidewalk needs releveling in sections

Front pavement needs repairs to cracked sections

Rectory

Foundation needs repairs, cracking near side entrance

Aluminum siding in need of replacement

Eves need painting as paint is peeling badly (unknown if rot is present)

Office

Front porch needs replacement.

Eves needs painting, paint is peeling.

Fence is falling in back yard. Needs replacement

4. St Joseph's Cemetery

Vault is unsafe, cement on ceiling is cracking (currently not used)

Multiple dead trees need to be removed for safety of people and head stones

5. St Patrick's Cemetery

No current Maintenance issues

Water would be a value to the property as there is no water present on property, well would have to be drilled. (rain barrel temporary fix)

THE GOOD OF THE DIOCESE OF SYRACUSE

Size of the local	Approx 180 Sq Miles		
Population trends of the city	Boonville, younger families, new families moving into the area. Otter Lake and Forestport, Some new seasonal population growth.		
Number of parishes to serve the population	1 Parish 3 worship sites		
Proximity of neighboring parish(es)	Distance between churches of Christ Our Hope St Joesph's (Boonville) to St Patrick's (Forestport) 8 Miles St Joseph's (Boonville) to St. Mary's (Otter Lake) 18 Miles S. Patrick's (Forestport) to St Mary's (Otter lake) 13 Miles Proximity of neighboring parish(es) St Mary's (Otter Lake) to St. Bartholomew Church Old Forge (Ogdensburg Diocese) 10 Miles St Joseph's Church (Boonville) to St. Martins Church (Port Leyden) (Ogdensburg Diocese) 7 Miles St Patrick's (Forestport) to St. Leo's (Holand Patent) 20 Miles		
Number of priests/ deacons available to serve the area	1 Priest, no deacons		
Pertinent trends of the city of (name) and / or the Diocese of Syracuse	NA		
Other			

OTHER OPTIONS FOR PASTORAL CARE CONSIDERED

Parish entrusted to a deacon	Not Recommended
Parish entrusted to a layperson under the direction of a priest	Not Recommended
Parish entrusted to a community of persons under the direction of a priest	Not Recommended

REASONS FOR POSSIBLE MODIFICATION (EXTINCTIVE MERGER)

1. Several buildings have fallen into disrepair	6. combining into one or two locations will help defray the cost of maintenance vs ministry
2. Possible closer relationship between parishioners, rather than his/her mentality.	
3. Increasing cost to run parish (utilities)	
4. Not enough funds to hire appropriate maintenance staff and address maintenance concerns.	
5. 52 miles roundtrip are driven by pastor on Sunday in Summer to serve each Church.	

ANNUAL UTILITY USAGE

<u>Location</u>	<u>Electric</u>	Gas	<u>Total</u>
St. Joseph's	\$5149.53	\$6126.02	\$11,275.55
St. Patrick's	\$7369.85	\$8457.40	\$15,827.25
St. Mary's	\$285.51	NA	\$ 285.51